

MODEL 710 FUNCTION AND CASUALTY TEST

TRACKING # TLW 9142H
PROJECT # 241095
ENGINEER - MIKE KEENEY

GUN #	MALFUNCTION					TOTAL
	AMMO R30061	AMMO R30065	AMMO R30066	AMMO R30063	AMMO R3306B	
XC 1052	0	0	0	0	0	0
XC 1054	2- bolt over ride	0	0	0	0	2
XC 1055	0	1- fail to reconnect	0	1- misfire	0	2
XC 1057	0	0	0	0	0	0
XC 1058	0	0	0	0	0	0
XC 1059	0	0	0	1- misfire	0	1
XC 1060	0	0	0	0	0	0
XC 1062	0	0	0	0	0	0
TOTALS	2	1	0	2	0	5

TOTAL OF 100 ROUNDS OF 5 REMINGTON AMMO TYPES SHOT THROUGH
EACH GUN FOR TOTAL OF 500 ROUNDS

TOTAL OF 4000 ROUNDS SHOT THROUGH 8 GUNS WITH TOTAL OF
5 MALFUNCTIONS

ET19776

Confidential - Subject to Protective Order
Williams v. Remington