

GUN#- X2 1054
DATE- 5-20-99
SHOOTER- JH

M/710 EET SAMPLE RIFLES
100 ROUND PROOF TEST

TRACKING # TLW 9142G
PROJECT # 241095

AMMO REM PRF 30-06			LOT# FLIG C0526		
		MALFUNCTIONS	INS.		MALFUNCTIONS
1	1	HEADSPACE MIN + .003	✓	51	1
2	2	HEADSPACE .003	✓	52	2
3	3	HEADSPACE .003	✓	53	3
4	4	HEADSPACE .003	✓	54	4
5	5	HEADSPACE Misfire .003	✓	55	5
6	6	HEADSPACE .003	✓	56	6
7	7	HEADSPACE .003	✓	57	7
8	8	HEADSPACE .003	✓	58	8
9	9	HEADSPACE .003	✓	59	9
10	10	HEADSPACE ✓ .003	✓	60	10 ✓
11	1			61	1
12	2			62	2
13	3			63	3
14	4			64	4
15	5	Misfire		65	5
16	6			66	6
17	7			67	7
18	8			68	8
19	9			69	9
20	10	HEADSPACE ✓ .004	✓	70	10 ✓
21	1			71	1
22	2			72	2
23	3			73	3
24	4			74	4
25	5			75	5
26	6			76	6
27	7			77	7
28	8			78	8
29	9			79	9
30	10	HEADSPACE ✓ .004	✓	80	10 ✓
31	1			81	1
32	2			82	2
33	3			83	3
34	4			84	4
35	5			85	5
36	6			86	6
37	7			87	7
38	8			88	8
39	9			89	9
40	10	HEADSPACE ✓ .004	✓	90	10 ✓
41	1	Seal pin fell out of fire		91	1
42	2	control - replaced		92	2
43	3			93	3
44	4	✓		94	4
45	5			95	5
46	6			96	6
47	7			97	7
48	8			98	8
49	9			99	9
50	10	HEADSPACE ✓ .004	✓	100	10 HEADSPACE ✓ .004

INS. = Inspected w/ bore scope
Misfire - 2 chamber, lugs

Look at firing pins, extractor
bolt lugs

ET19846