

GUN # - XC 1057
 DATE - 5-20-99
 SHOOTER - JTB

M710 EET SAMPLE RIFLES
 100 ROUND PROOF TEST

TRACKING # TLW 9142G
 PROJECT # 241095

AMMO REM PRF 30-06			LOT # D17C A0726		
		MALFUNCTIONS	INS.		MALFUNCTIONS
1	1	HEADSPACE MIN + .002 ✓	51	1	
2	2	HEADSPACE .002 ✓	52	2	
3	3	HEADSPACE .002 ✓	53	3	
4	4	HEADSPACE .002 ✓	54	4	
5	5	HEADSPACE .002 ✓	55	5	
6	6	HEADSPACE .002 ✓	56	6	
7	7	HEADSPACE .002 ✓	57	7	
8	8	HEADSPACE .003 ✓	58	8	
9	9	HEADSPACE .003 ✓	59	9	
10	10	HEADSPACE ✓ .003 ✓	60	10	✓
11	1		61	1	
12	2		62	2	
13	3		63	3	
14	4		64	4	
15	5		65	5	
16	6		66	6	
17	7		67	7	
18	8		68	8	
19	9		69	9	
20	10	HEADSPACE ✓ .003 ✓	70	10	✓
21	1		71	1	
22	2		72	2	
23	3		73	3	
24	4		74	4	
25	5		75	5	
26	6		76	6	
27	7		77	7	
28	8		78	8	
29	9		79	9	
30	10	HEADSPACE ✓ .003 ✓	80	10	✓
31	1	Sear pin fell out of fire	81	1	
32	2	control - nut came loose	82	2	
33	3	on screw - trigger pin	83	3	
34	4	loose - trigger fell out	84	4	
35	5		85	5	
36	6		86	6	
37	7		87	7	
38	8		88	8	
39	9		89	9	
40	10	HEADSPACE ✓ .003 ✓	90	10	✓
41	1		91	1	
42	2		92	2	
43	3		93	3	
44	4		94	4	
45	5		95	5	
46	6		96	6	
47	7		97	7	
48	8		98	8	
49	9		99	9	
50	10	HEADSPACE .004 ✓	100	10	HEADSPACE ✓ .004

Ins. = Inspected w/ bore scope
 chamber, lugs

Look at firing pin, extractor
 belt lugs

ET19848