

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303
PROJECT # 241314

CAL. 500 WIN M&A				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Torque - Scope Cross-bolt	Front 40 Rear 40		
BL	12-22-03	Headspace	min + .003	1	1
BL	12-22-03	Proof	OK		
BL	12-22-03	Headspace	min + .003		
JS/BL	12-22-03	Depth Front Take down	Screw hole		
BL	12-28-03	Firing Pin Indent	.018 - .019 Avg. .0186		
JS	12-29-03	Seal/Trigger Engagement	Arg. .0298		
JS	12-29-03	Seal Lift	.0154		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Headspace	Min + .004	1	2
SW/JS	1/13/04	Proof Rd			
SW/JS	1/13/04	Headspace	After proof Min + .004		
SW	1/15/04	300 Rd Basic Jack Function Test		200	202
SW	1-15-04	Headspace Min + .004	(Center Take down screw loose)	20	222
BL	1-16-04	Shoulder Fine	ok		
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

90
64

Confidential - Subject to Protective Order
Williams v. Remington

ET20026

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-30

TLW #: TLW1303

Date: 01 120 104

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min 1.004

☒ Sear Engagement: 1st. 0292 2nd. 0279 3rd. 0277

Ave. 0282 spec. .020" to .025" Ref Eng

☒ Trigger Pull: 1st. 4.801 2nd. 4.858 3rd. 4.733

Ave. 4.791 spec- 4 lb. to 5.5 lb. 0241

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Some wear on bolt face

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Locking lugs some wear Bolt stop worn

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding

TLW1303

Remington Confidential

ET20027