

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303
PROJECT # 241314

CAL. 500 WIN MAG				ROUNDS AT START-0	
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	Detonate - Scope Crosshair	Front 15 Rear 27		
BL	12-22-03	Headspace	min + .004		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	min + .004		
JS/BL	12-23-03	Depth Front Take down	Screw hole		
BL	12-23-03	Firing Pin Indent	.020 - .025 .019 Avg. .0193		
JS	12-29-03	Gear/Trigger Engagement	Avg. .034		
JS	12-29-03	Gear lift	.0162		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace	Min + .005		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min + .005		
sw	1/14/04	200 Rd Basic Jack Function Test		200	202
sw/BL	1/15/04	Headspace	Min + .005		
DM	1-16-04	Shoulder function test	X20 Rds. Shot clean	20	222
JS/BL	1-19-04	Clean & Inspect	See Inspection sheet		

Logform

— 44 —

ET20124

Confidential - Subject to Protective Order

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-9

TLW #: TLW1303

Date: 01 1 19 104

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min+.005

☒ Sear Engagement: 1st. .0323 2nd. .0325 3rd. .0326

Ave. .0324 spec. .020" to .025"

☒ Trigger Pull: 1st. 4.785 2nd. 5.001 3rd. 4.959

Ave. 4.915 spec- 4 lb. to 5.5 lb. .025

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Locking Lugs same wear; Bolt stop same wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box is protruding, receiver insert has a defect must be in the mold.

TLW1303

Remington Confidential

ET20125