

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .005	1	1
SW / BL	2/16/2004	PROOF ROUND			
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .006		
SW/JW/BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW / BL	2/17/04	TRIGGER PULL			
JK	2/19/04	200 Rd Jack Funct.		200	201
JW	2/25/04	500 Rd Ext Endur Test		500	701
BL	8/5/04	Clean / Inspection	See Inspection sheet		

Logform

—

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-6

TLW #: TLW1303

Date: 3 15 104

Inspector: BL

Round Level: 701

- ☒ Measure Headspace min .006
- ☒ Inspect Take Down Screws for loosening. Top screw 1/4 turn
- ☒ Sear Engagement: 1st .0363 2nd .0367 3rd .0368 Ave. .0366 spec- .025" to .030"
- ☒ Reset Sear Engagement if Required: 1st .0269 2nd .0271 3rd .0271 Ave. .0270
- ☐ Trigger Pull: 1st 4.865 2nd 5.053 3rd 5.089 Ave. 4.974 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st 2nd 3rd Ave.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface Locking lugs have some signs of wear
- ☒ Inspect stock for any signs of cracking or other failure: stock cracked at center screw hole
- ☒ Other items of note: Torque Top screw at 55 in lb - center screw 45 in lb

TLW1216

Remington Confidential

ET21079