

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

				ROUNDS AT START-0	
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	THW 1303		
JS	12/22/03	De-Torque Scope	Loose Bolt screws Front 25 Rear 25		
BL		Head space	Min + .005		
BL		Proof	OK	1	1
BL	12/22/03	Head space	Min + .005		
JS/BL	12/22/03	Depth Front Take down screw hole			
BL	12/23/03	Firing Pin Jidents	.021-.021-.022 Avg .0213		
JS	12-29-03	Seat/Trigger Engagement	Avg .0182		
JS	12-29-03	Seat / Pin	.0166		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min + .006		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Head space after proof	Min + .007		
Blee	1/15/04	Load Jack Funct. Test	Magazine Box has to come from Magazine well / 4 FTE Bolt head .0152	200	202
SW	1-15-04	Head space Min + .007	(Front Takedown screw loose)		
BL	1-16-04	Shoulder Fire	Bolt hard to close / 1 FTE	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

ET21333