

GUN # A-28
SHOOTER: SU
SERIAL # 71148866
CAL : 300 WIN MAG

200 RD BASIC JACK FUNCTION TEST

TLW1303
PROJECT # 241314

AMMO :		DATE : 1/15/04 ROUND LEVEL - 0	
MALFUNCTIONS		MALFUNCTIONS	
LOT #			
1	Rem A S300WA Lot# A16E B3523	51	
2		52	
3		53	
4		54	
5		55	
6		56	
7		57	
8		58	
9		59	
10		60	✓
11		61	Rem PRC300WC Lot# U10B B1
12		62	
13		63	
14		64	
15		65	
16		66	
17		67	
18		68	
19		69	
20	✓	70	
21	Rem PRC300WB Lot# T25 B B1	71	
22		72	
23		73	
24		74	
25	HTC	75	
26		76	
27		77	
28		78	
29		79	
30		80	✓
31		81	Rem A300W2 Lot# U27 P B1
32		82	
33		83	
34	HTC	84	
35		85	
36		86	
37		87	
38		88	
39		89	
40	✓	90	
41	Rem A300W1 Lot# T05 E B1	91	
42	Bolt Latch Failed HTC	92	
43		93	
44		94	
45		95	
46		96	
47		97	
48		98	
49		99	
50		100	✓

Front of Magazine bends out make hard to
set magazine in or out.
3 - Bolt hard to cycle over first round from magazine
1 - Bolt Latch Failed (bolt came out when cycled)

100

ET21365

GUN # A-28
SHOOTER: SW
SERIAL #
CAL : 300 WIN MAG

200 RD BASIC JACK FUNCTION TEST

TLW1303
PROJECT # 241314

AMMO :		DATE : 1/15/04 ROUND LEVEL - 100	
LOT #	MALFUNCTIONS		MALFUNCTIONS
1	Rem PRA300WC Lot # 4291A1	51	
2		52	
3		53	
4		54	
5		55	
6		56	
7		57	
8		58	
9		59	
10		60	
11		61	Fed 300 WGS Lot # 3043153
12		62	
13		63	
14		64	
15		65	
16		66	
17		67	
18		68	
19		69	
20		70	
21	Win SHV30WM2 Lot # RNO2	71	
22		72	
23		73	
24		74	
25		75	
26		76	
27		77	
28		78	
29		79	
30		80	
31		81	Fed P300WC Lot # 3043030
32		82	
33		83	
34		84	
35		85	
36		86	
37		87	
38		88	
39		89	
40		90	
41	Win X30WM2 Lot # 4TL20	91	
42		92	
43		93	
44		94	
45		95	
46		96	
47		97	
48		98	
49		99	
50		100	

300

ET21366