

Part Name:	trigger pivot pin	
Drawing Num:	B-300463	NOTE- Dimension identifiers will be provided on the prints supplied by engineering & the CAD group.
TLW Number:	1363	
Revision Level:		
Vendor:		INSTRUCTIONS:
Requisition #:		1. STAMP ALL PARTS WITH AN I.D. NUMBER AND CHANGE I.D. AT TOP OF PAGE CORRESPONDINGLY.
Material:		2. TAG PARTS ONLY IF STAMPING IS NOT POSSIBLE.
Hardness:		3. ENTER FEATURE DESCRIPTIONS WHEN POSSIBLE. (OPTIONAL)
Metallurgist:		4. WHEN COMPLETE, RETURN ALL PARTS TO ENGINEER IN ORIGINAL SHIPPING CARTON (IF POSSIBLE) AND DRAWING WITH IDENTIFIERS.
Engineer:	Mike Keeney	INSPECTOR NOTES:
Inspected by:	Steve Wade	
Date:	1/28/03	
Reviewed by:		
Date:		

Identifier	feature description	DIM	plus	minus	A-41	A-42	A-43	A-44	A-45	A-46	AVG	STDEV	Method
A	O.D.	0.1240	0.001	0.000	0.123	0.123	0.123	0.124	0.124	0.124	0.124	0.0005	MV
B	DISTANCE	0.3400	0.005	0.005	0.341	0.336	0.340	0.340	0.341	0.335	0.340	0.0012	MV
C											#DIV/0!	#DIV/0!	
D											#DIV/0!	#DIV/0!	
E											#DIV/0!	#DIV/0!	
F											#DIV/0!	#DIV/0!	
G											#DIV/0!	#DIV/0!	
H											#DIV/0!	#DIV/0!	
I											#DIV/0!	#DIV/0!	
J											#DIV/0!	#DIV/0!	
K											#DIV/0!	#DIV/0!	
L											#DIV/0!	#DIV/0!	
M											#DIV/0!	#DIV/0!	
N											#DIV/0!	#DIV/0!	
O											#DIV/0!	#DIV/0!	
P											#DIV/0!	#DIV/0!	
Q											#DIV/0!	#DIV/0!	
R											#DIV/0!	#DIV/0!	
S											#DIV/0!	#DIV/0!	
T											#DIV/0!	#DIV/0!	
U											#DIV/0!	#DIV/0!	
V											#DIV/0!	#DIV/0!	
W											#DIV/0!	#DIV/0!	
X											#DIV/0!	#DIV/0!	
Y											#DIV/0!	#DIV/0!	
Z											#DIV/0!	#DIV/0!	