

TRACKING # TLW1447
PROJECT #241314

				ROUNDS AT START-	
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/JS	4/25/04	Head space	Min +.002	TLW1447A	
"	"	Head space	Bolt Top GO won't close	"	
SW/JS	4/28/04	Proof Rd	OK Hammer bolt back	TLW1447B	1
"	4/26/04	Head space	Min +.003		
"	"	Head space	Bolt Top GO won't close		
SW	4/26/04	Firing Pin Indent	.018, .018, .017 Avg .0176	TLW1447D	
JS	4/28/04	Accuracy	3 groups of 5 shots 5 fouling shots	TLW1447T	20
B.Lee	5-4-04	Safe on/off Forces	See Inspection sheet	TLW1447G	
B.Lee	5-4-04	Bob Link / Pin Forces	"	TLW 1447 J	
B.Lee	5-4-04	Bore diameter	"	TLW 1447 L	
B.Lee	5-4-04	Twist Rate	"	TLW1447N	
SW/BL	5-6-04	Engagement		TLW1447E	
"	"	Trigger Pull		TLW1447F	
"	"	4.915 4.942	5.084 4.951 4.915 Avg. 4.961		
"	"	Reset Engagement	.0253, .0285, .0252 Avg. 02533	TLW1447X	
"	"	Reset Trigger Pull		TLW1447X	
"	"	4.474, 4.467, 4.516, 4.520, 4.673	Avg 4.530		
"	5-7-04	Saami Jar-off	PASS	TLW1447X	
"	"	Rotation Test	PASS	TLW1447Y	
SW	5-7-04	middle screw	stripped / replace From Gun A-1		
SW/BL	5/7/04	Saami Drop	PASS	TLW1447W	
SW/BL	5/6/04	"	checked in out (Broken pictures taken)		

FORMS.XLS