CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

	Model: 710 Extruded Receiver "Magnum Caliber"			
	Project: 241314	TLW #: TLW1689		
	Date: 2 / 24 / 05			
	Gun Test # 4-22	S/N 7/202749	4 	
	Round Level: /231	Inspector: BLEE		
Measure Headspa	ce <u>mint, 006</u> .			
Check Takedown	Screw Torque @ Disassembly: Frt2	⊅ , Center <u>30</u> , Rear <u>/3</u>	•	
Sear Engagement:	1 st 0268 2 nd 0281 3 rd 02	76 Ave. 10273 spec025" to.	.030"	
	ement if Required: 1 st . 2 nd .	3 rd Ave	-	
Trigger Pull:	1 st . <u>4885</u> 3 rd . <u>4.538</u> 3 rd . 4.563	Ave. 4.662 spec- 4.5 lb. to 6 l	lb.	
Reset Trigger Pull		_ 3 rd Ave		
Inspect Firesont	ol Insert for any signs of cracking or o	ther		
fathure.	AV			
	ч.	•		
other items of note:				
note				
7	•	•		
Torque Takedown	Screws @ Reassembly: SPEC- Frt- 75	5 in lbs, Center 30-35 in lbs, Rear-15 in lbs.		
			TLW1216	
	Remington Co	nfidential		