

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 / 24 / 05

Gun Test # A-32

S/N 71202753

Round Level: 1229

Inspector: B. LEE

83

- ☒ Measure Headspace min: .004
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 5, Center 20, Rear 15
- ☒ Sear Engagement: 1st .0301 2nd .0299 3rd .0298 Ave. _____ spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Trigger Pull: 1st 5.664 2nd 5.337 3rd 5.288 Ave. 5.427 spec- 4.5 lb. to 6 lb.
- ☐ Reset Trigger Pull if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note: _____
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET21986