

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 / 22 / 85

Gun Test # A-31

S/N 71202744

Round Level: 719

Inspector: B. LEE

83

- ☒ Measure Headspace min+.006
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 20, Center 25, Rear 15
- ☒ Sear Engagement: 1st .0302 2nd .0293 3rd .0297 Ave. .0297 spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st 2nd 3rd Ave.
- ☒ Trigger Pull: 1st 5.866 2nd 5.353 3rd 5.253 Ave. 5.491 spec- 4.5 lb. to 6 lb.
- ☐ Reset Trigger Pull if Required: 1st 2nd 3rd Ave.
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. ok
- ☐ Other Items of note:
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET22022