

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314

TLW #: TLW1689

Date: 2/22/05

Gun Test # A-11

S/N 71202772

Round Level: 701

Inspector: B. Lee

83

- ☒ Measure Headspace min .003
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 20, Center 25, Rear 15
- ☒ Sear Engagement: 1st .0245 2nd .0252 3rd .0250 Ave. .0249 spec- .020" to .025"
- ☐ Reset Sear Engagement if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Trigger Pull: 1st 5.469 2nd 4.478 3rd 4.421 Ave. 4.769 spec- 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☐ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note: _____
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET22046