

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314

TLW #: TLW1689

Date: 3 12 1 05

Gun Test # A-11

S/N 71202772

Round Level: 2211

Inspector: B. Lee

83

- ☒ Measure Headspace min^t. 003
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 40, Center 35, Rear 10
- ☒ Sear Engagement: 1st. .0242 2nd. .0238 3rd. .0238 Ave. .0239 spec-.020" to .025"
- ☐ Reset Sear Engagement if Required: 1st. nd 3rd. Ave.
- ☒ Trigger Pull: 1st. 3.791 2nd. 3.790 3rd. 3.685 Ave. 3.755 spec- 4 lb. to 5.5 lb.
- ☒ Reset Trigger Pull if Required: 1st. 4.513 2nd. 4.455 3rd. 4.418 Ave. 4.462
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note: _____
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET22069

Confidential - Subject to Protective Order
Williams v. Remington