

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Model: 710 Extruded Receiver "Std. Caliber"

TLW #: TLW1689

Gun Test # A-2

S/N 71202775

Round Level: 701

Inspector: B. LEE

☒ Check Takedown Screw Torque @ Disassembly: Frt 45, Center 30, Rear 10

☐ **Reset Sear Engagement if Required:** 1st _____ 2nd _____ 3rd _____ Ave. _____☒ **Reset Trigger Pull if Required:** 1st. 5.278 2nd. 5.091 3rd. 5.059 Ave. 5.143

☒ Inspect Firecontrol Insert for any signs of cracking or other failure. *OK*

☐ Other items of note:

☒ **Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.**

Remington Confidential

Confidential - Subject to Protective Order
Williams v. Remington