

CONFIDENTIAL

Remington Arms Company Inc.  
Research & Development Technical Center  
315 West Ring Road  
Elizabethtown, KY 42701

## Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-4

TLW #: TLW1216

Date: 8 / 20 / 03

Inspector: SW/BL

Round Level: 222

☒ Measure Headspace min+.007

☒ Sear Engagement: 1<sup>st</sup>. .0249 2<sup>nd</sup>. .0249 3<sup>rd</sup>. .0250

Ave. .02493 spec. .020" to .025"

83

☐ Reset Sear Engagement if Required: 1<sup>st</sup>.        2<sup>nd</sup>.        3<sup>rd</sup>.       

Ave.       

☒ Trigger Pull: 1<sup>st</sup>. 4.219 2<sup>nd</sup>. 4.412 3<sup>rd</sup>. 4.336

Ave. 4.320 spec. 4 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1<sup>st</sup>.        2<sup>nd</sup>.        3<sup>rd</sup>.       

Ave.       

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: very little wear on bolt stop

☒ Inspect stock for any signs of cracking or other

failure. Lower corner of recoil bracket has cracks on stock  
crack on middle take down screw hole

☒ Other items of

note: Top of magazine box has some protrusion, wear in  
magazine latch area

TLW1216

Remington Confidential

ET22542