CONFIDENTIAL

Remington Arms Company Inc. Research & Development Technical Center 315 West Ring Road Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER Project: 241230	}
Rifle: A . 3 TLW #: TLW1530	
Date: 7 /14 /04 Inspector: 5 1/1	
Round Level: 341	. 4 3. u.
Measure Headspace Min + 1007	
Sear Engagement: 1st.,0360 2nd0363 3rd0359 Ave0360 spec020" to 025"	3 83
☐ Reset Sear Engagement if Required: 1 st . 2 nd . 3 rd . Ave.	All A
Trigger Pull: 1st, 4.477 2nd, 4, 534 3rd, 4, 567 Ave 4, 532 spec-4 lb. to 5.5 lb.	
☐ Reset Trigger Pull if Required: 1 st	
Inspect cam surface, locking lugs and bolt stop for signs of excessive	
wear: Locking by narmal wear	~
Inspect stock for any signs of cracking or other fathere.	
	_
(items of	
nate:	_
	_
·	
T ·	LW1216
Remington Confidential	

ET22772