

CONFIDENTIAL

Remington Arms Company Inc.  
Research & Development Technical Center  
315 West Ring Road  
Elizabethtown, KY 42701

## Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-5

TLW #: TLW1530A

Date: 7 / 27 / 04

Inspector: SN

Round Level: 241

- ☒ Measure Headspace Min +.003 83
- ☒ Sear Engagement: 1<sup>st</sup>. .0250 2<sup>nd</sup>. .0252 3<sup>rd</sup>. .0249 Ave. .02503 spec. .020" to .025"
- ☐ Reset Sear Engagement if Required: 1<sup>st</sup>. \_\_\_\_\_ 2<sup>nd</sup>. \_\_\_\_\_ 3<sup>rd</sup>. \_\_\_\_\_ Ave. \_\_\_\_\_
- ☒ Trigger Pull: 1<sup>st</sup>. 4.299 2<sup>nd</sup>. 4.377 3<sup>rd</sup>. 4.128 Ave. 4.268 spec. 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1<sup>st</sup>. \_\_\_\_\_ 2<sup>nd</sup>. \_\_\_\_\_ 3<sup>rd</sup>. \_\_\_\_\_ Ave. \_\_\_\_\_
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: OK
- ☒ Inspect stock for any signs of cracking or other failure: OK
- ☐ Other items of note: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

TLW1216

Remington Confidential

ET22825