

CONFIDENTIAL

Remington Arms Company Inc.  
Research & Development Technical Center  
315 West Ring Road  
Elizabethtown, KY 42701

## Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-8

TLW #: TLW1530

Date: 7 / 27 / 04

Inspector: SW

Round Level: 241

☒ Measure Headspace Min 4.003

☒ Sear Engagement: 1<sup>st</sup>. .0264 2<sup>nd</sup>. .0264 3<sup>rd</sup>. .0262

Ave. .02626 spec- .020" to .025"

☐ Reset Sear Engagement if Required: 1<sup>st</sup>. \_\_\_\_\_ 2<sup>nd</sup>. \_\_\_\_\_ 3<sup>rd</sup>. \_\_\_\_\_

Ave. \_\_\_\_\_

☒ Trigger Pull: 1<sup>st</sup>. 4.916 2<sup>nd</sup>. 5.002 3<sup>rd</sup>. 5.054

Ave. 4.991 spec- 4 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1<sup>st</sup>. \_\_\_\_\_ 2<sup>nd</sup>. \_\_\_\_\_ 3<sup>rd</sup>. \_\_\_\_\_

Ave. \_\_\_\_\_

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: OK

☒ Inspect stock for any signs of cracking or other

failure. OK

☐ Other items of

note: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

TLW1216

Remington Confidential

ET22893