

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-10

TLW #: TLW1530

Date: 8 / 30 / 04

Inspector: SW

Round Level: 741

☒ Measure Headspace Min + .003

☒ Sear Engagement: 1st .0357 2nd .0359 3rd .0355 Ave. .03570 spec. .020" to .025" 83

☒ Reset Sear Engagement if Required: 1st 2nd 3rd Ave.

☒ Trigger Pull: 1st 4.370 2nd 4.552 3rd 4.456 Ave. 4.459 spec. 4 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1st 2nd 3rd Ave.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs normal wear

☐ Inspect stock for any signs of cracking or other failure. "Normal" 45° crack - shorter's left longer than right

☐ Other items of note: OK

TLW1216

Remington Confidential

ET22932