

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START- RDS. FIRED	TOTAL RDS.
B.Lee	7-12-04	Initial Handspace	min 1.004		
B.Lee	7-13-04	PRMF	OK		
B.Lee	7-13-04	Re-measure Handspace	min 1.004		
B.Lee	7-13-04	Indents	.019-.1019-.018 Avg. .0186		
SW	7-14-04	Engagement	See data sheet		
SW	7-15-04	See Firing Pin Head Engagement	See data sheet		
SW	7-15-04	Trigger Pull	See data sheet		
B.L	7-15-04	Safety on/off Force	See data sheet		
B.L	7-15-04	Push opening/closing force	See data sheet		
SW	7-16-04	Seal Lift	See data sheet		
B.L	8-5-04	200 Rpt Basic Jack Function Test	TLW1530N	100	101
B.L	8-10-04	200 Rpt Basic Jack Function Test	TLW1530N	100	201
JS	8-10-04	Receiver - Modified	Machined chamber for aid in feeding. <i>Remove</i>		
SW/JS	8/13/04	Shoulder Function Test	0 Malfunctions	TLW 1530 O	221
BL/JS	8/13/04	Accuracy		20	241
SW	8/16/04	Clear Int Inspect	OK Handspace Min 1.005		
SW/JW	8/30/04	Swami Juv-off	Pass	TLW1530Y	
SW/JW	8/31/04	Swami Rotation	Pass	TLW1530Z	
SW/JW	8/31-04	Swami Drop	Pass (Reheating off insert)	TLW1530AA	
SW	9/1/04		Took insert from A-7		
SW/JW	9-2-04	Extended Juv-off	18" Pass	TLW1530AB	
SW/JS	9-2-04	Extended Juv-off	34" Pass	TLW1530AB	
SW/JW	9-2-04	Extended Juv-off	36" Pass	TLW1530AD	
SW/JW	9/3/04	Extended Juv-off	48" Pass Broken twg off insert	TLW1530AB	
SW/JW		Extended Juv-off	Put in A-13		
SW/JW	9/3/04	Extended Rotation	Broken stock	TLW1530AC	
SW/JW	9-3-04	Extended Drop	Replaced stock from A-14		
SW/JW	9-3-04	Extended Drop	72" Pass Broken twg off insert TLW1530AD		
SW/JW	9-3-04	Extended Drop	Took insert from A-10, Put in A-13		
SW/JW	9-3-04	Extended Drop	96" FAIL	TLW1530AD	
SW/JW	9-3-04	Extended Drop	Broken Insert		
SW	9/9/04	Put insert from A-1 into A-13			
SW	10/30/04	Safety Operation (Swami)	PASS (See Note)	TLW1530L	
SW	10/14/04	40lb. Trigger Pull Test (Remington)	PASS	TLW1530M	

Note! Stripped Engagement Screw in Housing
Pushing trigger from rear of trigger forward

DAILY DATA SHEET

Remington Arms Confidential

Page 1