

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-15

TLW #: TLW1530

Date: 9 / 2 / 04

Inspector: SW

Round Level: 1731

☒ Measure Headspace Min 7.006

☒ Sear Engagement: 1st .0334 2nd .0333 3rd .0333

Ave. .0333 spec. .020" to .025"

☐ Reset Sear Engagement if Required: 1st _____ 2nd _____ 3rd _____

Ave. _____

☒ Trigger Pull: 1st 5.46 2nd 5.35 3rd 5.44

Ave. 5.40 spec. 4 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1st _____ 2nd _____ 3rd _____

Ave. _____

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: locking lugs normal wear, bolt stop little wear

☒ Inspect stock for any signs of cracking or other

failure. still cracked - no worse

☒ Other items of

note: OK

TLW1216

Remington Confidential

ET23044