

Remington Model 710
Trial and Pilot Test
100 rd. Function Test
B-11 to B-20

100 rd. Jack Function Test
TLW0300Z
11/20/00

Guns B-11 to B-20

This is a 100 rd. Basic Jack Function Test performed in the Function & Casualty Range using the std. Remington test jacks.
Only Remington ammo was used, 20 rds. ea. of 5 types.

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-11	71001534	Rem. L30062, 150 GR. MC	M02 GC1	1 stem low, mag follower binding, replaced mag box
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	1 stem low, mag follower binding, replaced mag box
		Rem. R30064, 180 gr.SP	K28G B 14	0
		Rem. R30065, 180 gr. PSP	L20 DA28	0
		Rem. R30067, 220 gr. SP	M06N B26	0
Technician-	Bob Lee			
Comments Noted- Grip cap came off @ 20 rds.				
Note- Replaced magazine with a new mag. supplied by Mayfield, problem reoccurred, replaced and resumed testing with no further malfunctions.				

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-12	71001535	Rem. L30062, 150 GR. MC	M02 GC1	1 stem low, mag follower binding, replaced mag box
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	0
		Rem. R30064, 180 gr.SP	K28G B 14	0
		Rem. R30065, 180 gr. PSP	L20 DA28	bolt handle broke off, replaced bolt
		Rem. R30067, 220 gr. SP	M06N B26	0
Technician- Bob Lee				
Comments Noted- Lubed bolt @ 40 rds.				
Replacement bolt came from gun B-1 and had 510 rds. on it.				
Note- Replaced magazine with a new mag. supplied by Mayfield and resumed testing with no further malfunctions.				

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-13	71001539	Rem. L30062, 150 GR. MC	M02 GC1	0
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	0
		Rem. R30064, 180 gr.SP	K28G B 14	1 stem low, mag follower binding, replaced mag box
		Rem. R30065, 180 gr. PSP	L20 DA28	0
		Rem. R30067, 220 gr. SP	M06N B26	0
Technician- Bob Lee				
Comments Noted- Mag box binding, hard to remove				
Note- Replaced magazine with a new mag. supplied by Mayfield and resumed testing with no further malfunctions.				

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-14	71001559	Rem. L30062, 150 GR. MC	M02 GC1	0
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	0
		Rem. R30064, 180 gr.SP	K28G B 14	0
		Rem. R30065, 180 gr. PSP	L20 DA28	0
		Rem. R30067, 220 gr. SP	M06N B26	0
Technician-	Bob Lee			
Comments Noted-	Mag box binding, hard to remove			

GUN #	Serial #	Ammo Types	Lot #	Malfunctions
B-15	71001578	Rem. L30062, 150 GR. MC	M02 GC1	0
		Rem. PRT3006B, 165 gr. NBT	M01 NC0525	0

ET34199