

PART DESCRIPTION	Part #	Proposed Process	Capital Dollars	Operations Dollars	Material \$	Labor \$	Fixed Overhead \$	Variable Overhead \$	Total Overhead \$	Estimated Piece Price
Bolt Stop	300345	PM/Heat Treat/Color	\$ 6,000	\$ 3,500	\$ 0.01	\$ 0.11	\$ 0.01	\$ 0.44	\$ 0.45	\$ 0.57
Receiver Plug Screws (4)	17034	A/U M/700	N/A	N/A	\$ 0.12	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.01	\$ 0.13
Recoil Bracket	300361	Purchase & Color	\$ 550	\$ 250	\$ 0.19	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.19
Bolt Body Assembly	????	Braze & Finish	\$ 36,500	\$ 4,000	\$ 8.32	\$ 0.60	\$ 0.23	\$ 1.33	\$ 1.56	\$ 10.49
Bolt Body	300339	Purchase	\$ -	\$ -	\$ 5.53	\$ -	\$ -	\$ -	\$ -	\$ 5.53
Bolt Handle	300370	Bend to Form	\$ 28,430	\$ 2,150.00	\$ 2.66	\$ 0.13	\$ 0.06	\$ 0.31	\$ 0.37	\$ 3.17
Bolt Handle Blank	300360	Purchase	\$ -	\$ 800	\$ 2.66	\$ -	\$ -	\$ -	\$ -	\$ 2.66
Bolt Handle Pin	300329	Purchase	\$ -	\$ 350	\$ 0.07	\$ -	\$ -	\$ -	\$ -	\$ 0.07
Bolt Handle Brazing Shim	300366	Purchase	\$ -	\$ 125	\$ 0.06	\$ -	\$ -	\$ -	\$ -	\$ 0.06
Bolt Head Assembly	????	Assemble	\$ -	\$ 1,000	\$ 2.57	\$ 1.88	\$ 0.76	\$ 4.16	\$ 4.92	\$ 9.37
Bolt Head	300338	Machined	\$ 150,000	\$ 800	\$ 1.60	\$ 1.59	\$ 0.70	\$ 3.69	\$ 4.39	\$ 7.57
Extractor	93712	A/U M/700	N/A	N/A	\$ 0.77	\$ 0.00	\$ 0.00	\$ 0.01	\$ 0.01	\$ 0.78
Ejector	300342	Purchase & Color	\$ -	\$ 900	\$ 0.16	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.16
Ejector Spring	????	Purchase	\$ -	\$ -	\$ 0.03	\$ -	\$ -	\$ -	\$ -	\$ 0.03
Ejector Pin	94555	A/U M/700	N/A	N/A	\$ 0.01	\$ -	\$ -	\$ -	\$ -	\$ 0.01
Bolt Assembly Pin	300330	Purchase & Color	\$ -	\$ 400	\$ 0.22	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.22
Firing Pin Assembly	????	Assemble	\$ 7,500	\$ 1,000	\$ 3.28	\$ 0.54	\$ 0.12	\$ 1.18	\$ 1.30	\$ 5.12
Bolt Plug	300368	Purchase	\$ -	\$ -	\$ 0.94	\$ -	\$ -	\$ -	\$ -	\$ 0.94
Bolt Plug Insert	300346	Purchase	\$ 2,250	\$ 300	\$ 0.29	\$ -	\$ -	\$ -	\$ -	\$ 0.29
Firing Pin	300334	Purchase & Color	\$ -	\$ 400	\$ 0.30	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.30
Firing Pin Tip	300335	Purchase & Heat T	\$ 1,000	\$ 1,100	\$ 1.28	\$ 0.02	\$ 0.01	\$ 0.05	\$ 0.05	\$ 1.35
Firing Pin Head	300336	MM	\$ 25,500	\$ 8,900	\$ 0.33	\$ 0.26	\$ 0.02	\$ 0.61	\$ 0.63	\$ 1.22
Firing Pin Spring	????	Purchase	\$ -	\$ -	\$ 0.14	\$ -	\$ -	\$ -	\$ -	\$ 0.14
Front Sight	94084	A/U M/700	N/A	N/A	\$ 0.61	\$ 0.25	\$ 0.05	\$ 0.51	\$ 0.56	\$ 0.82
Front Sight Ramp	94657	A/U M/700	N/A	N/A	\$ 0.02	\$ 0.26	\$ 0.07	\$ 0.78	\$ 0.85	\$ 1.13
Front Sight Ramp Screws (2)	28505	A/U M/700	N/A	N/A	\$ 0.09	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.09
Rear Sight Assembly	103146	A/U M/700	N/A	N/A	\$ 0.28	\$ 0.91	\$ 0.15	\$ 1.86	\$ 2.02	\$ 3.20
Elevation Screw	90906	A/U M/700	N/A	N/A	\$ 0.02	\$ -	\$ -	\$ -	\$ -	\$ 0.02
Rear Sight Aperture	94333	A/U M/700	N/A	N/A	\$ 0.00	\$ 0.08	\$ 0.02	\$ 0.22	\$ 0.23	\$ 0.31
Rear Sight Base	103531	A/U M/700	N/A	N/A	\$ 0.16	\$ 0.24	\$ 0.02	\$ 0.56	\$ 0.58	\$ 0.98
Rear Sight Slide	94335	A/U M/700	N/A	N/A	\$ 0.07	\$ 0.38	\$ 0.07	\$ 0.75	\$ 0.82	\$ 1.28
Windage Screw	90904	A/U M/700	N/A	N/A	\$ 0.02	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.02
Rear Sight Base Screw (2)	28505	A/U M/700	N/A	N/A	\$ 0.09	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.00	\$ 0.09
M/710 ESTIMATE - REV 6 - CLASS 2 ESTIMATE										
	Part #	Proposed	Capital	Operations	Material	Labor	Fixed Overhead	Variable Overhead	Total Overhead	Estimated