## Phillip Reesor

From: Reesor, Phillip K.
Sent: 08/19/2003 08:16:41 AM

To: Franz, Scott

CC:

BCC:

Subject: RE: Quick Status

710- Starting back on this today, we are at clean & inspect stage after shoulder function, going into accuracy next. I'll ssent you some data.
I'll contact John Trull about the 597 rifles.

597 Non-ISS Safety Button- all housings are in and we are starting on that today.

504- finished all extended testing yesterday.

----Original Message----

From: Franz, Scott

Sent: Tuesday, August 19, 2003 7:49 AM To: Reesor, Phillip K.

To: Reesor, Phillip K. Subject: Quick Status Importance: High

Phillip,

Do me a favor a put together a quick status on 740 Magnum testing. Nothing elaborate, what's done and a brief on results to date for function, meas, etc.. Also a reminder to send Trull a note requesting all 10 597 LR's for the audit be sent to E-town. Tell him to not worry about cleaning his, we'll do that. And finally, have we received all Non-ISS trigger assemblies back from Mayfield? If we have what's the outlook for testing these?

Just want to be in a position to answer questions before they start. Last question, where are we on 504 DAT Drop testing?

I'll let you know if and when we have a conf. call with the BATF. WOuld like you there.

Thanks, Scott

Scott Franz
Manager of Research and Technology
Remington Arms Company, inc.
Research & Development Technology Center
Telephone: (270) 769-7607 - (0) for Operator
FAX: (270) 737-9576

MY E-MAIL HAS CHANGED to scott.franz@remington.com

