

B-15	REM R30065 180GR	40								
	REM R30067 220GR	40								
	REM UMC L30062 150GR	40	NO MALFUNCTIONS							
	REM PRT3006B 165GR	40								
	REM R30063 150GR	40								
	TOTAL	200	0	0		0	0		0	
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN	MAG BOX	MISFIRE	BOLT CAME OUT
B-16	REM R30065 180GR	40								
	REM R30067 220GR	40								
	REM UMC L30062 150GR	40								
	REM PRT3006B 165GR	40								
	REM R30063 150GR	40	1							
	TOTAL	200	1	0		0	0		0	
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN	MAG BOX	MISFIRE	BOLT CAME OUT
B-17	REM R30065 180GR	40								
	REM R30067 220GR	40								
	REM UMC L30062 150GR	40	NO MALFUNCTIONS							
	REM PRT3006B 165GR	40								
	REM R30063 150GR	40								
	TOTAL	200	0	0		0	0		0	
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN	MAG BOX	MISFIRE	BOLT CAME OUT
B-18	REM R30065 180GR	40								
	REM R30067 220GR	40								
	REM UMC L30062 150GR	40								
	REM PRT3006B 165GR	40								
	REM R30063 150GR	40				1				
	TOTAL	200	0	0		1	0		0	
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN	MAG BOX	MISFIRE	BOLT CAME OUT
B-19	REM R30065 180GR	40								
	REM R30067 220GR	40								
	REM UMC L30062 150GR	40	NO MALFUNCTIONS							

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.06R0002847

ETE00002846