

PROJECT# 241095									
TLW 0010AA									
BASIC JACK FUNCTION TEST									
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN	MAG BOX	MISFIRE BOLT CAME OUT
B-11	REM R30065 180GR	20	1						1
	REM R30067 220GR	20							1
	REM UMC L30062 150GR	20							2
	REM PRT3006B 165GR	20							1
	REM R30063 150GR	20							
	TOTAL	100	1	0		0	0		5
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN	MAG BOX	MISFIRE BOLT CAME OUT
B-12	REM R30065 180GR	20							
	REM R30067 220GR	20							2
	REM UMC L30062 150GR	20							
	REM PRT3006B 165GR	20							
	REM R30063 150GR	20							1
	TOTAL	100	0	0		0	0		3
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN	MAG BOX	MISFIRE BOLT CAME OUT
B-13	REM R30065 180GR	10							
	REM R30067 220GR	10							1
	REM UMC L30062 150GR	10							
	REM PRT3006B 165GR	10							
	REM R30063 150GR	10							
	TOTAL	50	0	0		0	0		1
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN	MAG BOX	MISFIRE BOLT CAME OUT
B-14	REM R30065 180GR	10							
	REM R30067 220GR	10							
	REM UMC L30062 150GR	10	NO MALFUNCTIONS						
	REM PRT3006B 165GR	10							
	REM R30063 150GR	10							
	TOTAL	50	0	0		0	0		0
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN	MAG BOX	MISFIRE BOLT CAME OUT

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.06R0002890

ETE00002889