CONFIDENTIAL

Remington Arms Company Research & Development Technical Center 315 West Ring Road Elizabethtown, KY 42701

- Beginning separation or material stretching in front of the case head indicating excessive headspace
 or excessive pressure as stated above.
- Any cartridge case failure indicating a firearm fault
- In addition, the spent proof round should be examined for the presence of unusual deformation, split case or split head, and for any evidence of a pierced primer. Any of these conditions may be indicative that highpressure gases may have vented into the action where other damage to components may have occurred.
- Take note of any indication of significant gas leakage, if present, it may indicate that the firearm was not subjected to full proof pressures and the proof test would then be invalid and would require re-proofing.
- A firearm is only properly proofed when the cartridge has been fired without evidence of significant gas leakage.
- Save the spent proof case in a Zip-Lock plastic bag and label and place in the data packet for further
 reference. If any parts were broken or otherwise damaged, place these parts in the same bag as the proof
 case and label. Place a label on the firearm and withdraw the firearm from the test.
- Each sample firearms' headspace (see following procedure "TLW0300G Re-Measure Headspace after Proof") must remain in range from min. to min. +.007" after proofing, with no individual firearm's headspace to grow more than .002" after fixing one proof round. After successful proofing, the right lug on the bolt head will be marked in the center (i.e. center of top to bottom and center or front to rear) of the lug with a center punch to indicate that is has been proofed.
- After proof, if the firearm passes the inspection and headspace has been measured (see next section of test plan), stamp the firearm on the barrel with an authorized Remington proof stamp. Locate the proof mark on the right rear of the barrel in the specified location for the Remington proof stamp. DO NOT STAMP if the headspace exceeds Min + .009".
- Because of the higher pressures involved in shooting proof cartridges, adequate precautions, both
 mechanical and procedural should be taken to protect personnel performing the firearms proof testing. To
 this end, the firearm should be securely mounted, completely shielded from the operator and firing
 accomplished by a remote control method.

Data Required

Rifle serial number

J.R.Snedeker

Page 13 of 51

9:45 AM 9/21/00

TLW0300

Remington Confidential

Revision # 0