

CONFIDENTIAL

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

Comments: Magazine box became very difficult to remove from gun, straightened magazine box 200 rounds into test & continue.

RIFLE NUMBER	SERIAL NUMBER	AMMUNITION TYPE	LOT NUMBER	ROUNDS FIRED	MALFUNCTIONS
C-11	71002555	Rem. R30063, 150 gr. BR PT	326N B97	160	Mag. box bottom came @ 24 rounds
		Win. S3006XB, 150 gr.	ME51	50	3 Stem Low
		Win. SHV30064, 180 gr.	35PC52	50	0
		Fed. P3006G, 150 gr.	A146782340	70	0
		Fed. 3006b, 180 gr.	41047X228	10	0
		Fed. P3006Q, 165 gr.	010614X250	30	0
		Rem. L30062, 150 gr. MC	M03G B1	20	0
		Win. SBST3006XA, 168 gr.	04RK31	10	0
Technician:	J. Arnold				
Comments:	None				
RIFLE NUMBER	SERIAL NUMBER	AMMUNITION TYPE	LOT NUMBER	ROUNDS	MALFUNCTIONS

Jan. '01 Trial & Pilot Test - Remington M710 Centerfire Rifle;
R & D Technical Center Project No. 241039; TLW 0300
File: E:\Test Reports\Firearms Tests\710 T&P_3006\M710_T&P_REPORT_JAN01_Rev0.doc

Page 32

CONFIDENTIAL

REV 0 05/01/06 10:17 AM

Subject to Protective Order - Williams v. Remington

BARBER 5.30.06R000000003

E7E00001942