

## Glen Sietsema

---

**From:** Sietsema, Glen D.  
**Sent:** 01/13/2006 07:22:20 AM  
**To:** Doolittle, James F.  
**CC:**  
**BCC:**  
**Subject:** FW: Routing: 301435 Rev PK 1st article.doc

Jim,  
Should the SPL side plate first article go through the Met Chem Lab?

It looks like they missed the inspection.  
If so let me know where they are and I'll get them inspected.

Glen D. Sietsema  
Metallurgical Engineer  
Remington Arms Company, Inc.  
14 Hoeffer Ave.  
Ilion, NY 13357  
(315) 895-3234 Phone  
(315) 895-3407 FAX  
glen.sietsema@remington.com  
visit us at [www.Remington.com](http://www.Remington.com)

-----Original Message-----

From: Golem, Todd E.  
Sent: Friday, January 13, 2006 7:02 AM  
To: Sietsema, Glen D.  
Cc: Morningstar, Dean E.  
Subject: RE: Routing: 301435 Rev PK 1st article.doc

Glen,

I don't believe these went to MetLab. This is why the Met inspector space is blank. The 1st Article is for dimensional only. These are Jim Doolittle's spl parts. He has them.

Regards,  
Todd E Golem - QE

-----Original Message-----

From: Morningstar, Dean E.  
Sent: Friday, January 13, 2006 6:58 AM  
To: Sietsema, Glen D.  
Cc: Golem, Todd E.  
Subject: RE: Routing: 301435 Rev PK 1st article.doc

Glen,  
I just forwarded the electronic document. I did not initiate the first article report.

Please contact Todd Golem on your question below.

Regards  
Dean

-----Original Message-----

From: Sietsema, Glen D.  
Sent: Thursday, January 12, 2006 5:36 PM  
To: Morningstar, Dean E.  
Subject: RE: Routing: 301435 Rev PK 1st article.doc

Dean,  
Were these routed through the Met Chem Lab.? I don't see the usual sign off.

Glen D. Sietsema  
Metallurgical Engineer  
Remington Arms Company, Inc.  
14 Hoefler Ave.  
Ilion, NY 13357  
(315) 895-3234 Phone  
(315) 895-3407 FAX  
glen.sietsema@remington.com  
visit us at [www.Remington.com](http://www.Remington.com)

-----Original Message-----

From: Morningstar, Dean E.  
Sent: Thursday, January 12, 2006 1:39 PM  
To: Sietsema, Glen D.  
Subject: Routing: 301435 Rev PK 1st article.doc

The attached document has a routing slip. When you are done reviewing this document, choose Next Routing Recipient from the Microsoft Office Word Send To menu on the File menu to continue the routing.