

Cust. Complaint ✓1... No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700GENERAL CONDITION: FAIR R #: 11955OUTSIDE WORK: SCOPE MOUNTED DATE: 6-3-71FROM: NATIONAL PARK SERVICEFIRED AMMO TYPE: - KANULUI MAIL, HAWAII& CONDITION: _____ GUN #: 6258362PROOF: R.E.P.-E INSP.: 11 TEST: 27 CODE: 05 = 7/69HEADING: O.K. GA./CAL.: 3006BRECH OPENING: - CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

10 BROKEN, ETC. COMPONENTS.CONNECTOR CLEARANCE ON TRIGGER = 1.070 MID = 1.079 - .006TRIGGER CLEARANCE ON CONNECTOR = 1.089 MID = 1.083 + .006CONNECTOR-SEAR ENGAGEMENT = .020 EXCESSIVELUBRICANT OIL DIRTY, TRIGGER PULL FOUR POUNDS.COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.INCIDENT: TRIGGER CONNECTOR FAILED TO RETRACT.COMMENTS: CAN NOT DUPLICATE CUSTOMER'S MALFUNCTION.THE TRIGGER & TRIGGER CONNECTOR NOT TO MODELDRAWING PERMIT SEAR-TRIGGER CONNECTOR INTERFERENCEFAILURE TO RETRACT.PLAINTIFF'S
EXHIBIT

3273

1 of 1

AL 0029805