

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 23406
OUTSIDE WORK: NO DATE: 11-2-70
FROM: OCONTO, WIS.
FIRED AMMO TYPE: _____
& CONDITION: _____ GUN #: 6248578
PROOF: _____ INSP.: _____ TEST: _____ CODE: PS-6/69
HEADING: _____ GA/CAL.: 7MM
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: _____ APPROVED: _____
CHAMBER: _____ APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN.

COMPLAINT: FIRES WHEN SAFE IS REMOVED & WONT COCK
AT TIMES.

INCIDENT: _____

COMMENTS: MALEFUNCTION WAS CAUSED BY THE BROKEN
TRIGGER CONNECTOR.

PLAINTIFF'S
EXHIBIT

3287

1 of 1

AL 1129820