

Custom Complaints

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: NEW R #: 26143
OUTSIDE WORK: NO DATE: 11-12-70
FROM: DAKIN SALES CORP. CO.
FIRED AMMO TYPE: - BANGOR, MAINE
& CONDITION: _____ GUN #: 6219140
PROOF: R.E.P. INSP.: _____ TEST: 41 CODE: LS-2/69
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: - APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN.

COMPLAINT: "WILL NOT STAY COCKED"

INCIDENT: FOLLOWS DOWN

COMMENTS: THE BROKEN CONNECTOR MAKES RETRACTION
UNDER SEAR UNCONTROLLABLE. THE CONNECTOR
FAILING TO RETRACT CAUSES FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3289

1 of 1