

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 22775
OUTSIDE WORK: NO DATE: 10-15-70
FROM: MARKLEYSBURG, PA.
FIRED AMMO TYPE: _____
& CONDITION: _____
PROOF: R.E.P. INSP.: 9 TEST: _____
HEADING: O.K. GA./CAL.: 22-250
BREECH OPENING: — CHECKED BY: C. PROSSER
RECOIL SHOULDERS: — APPROVED: _____
CHAMBER: — APPROVED: _____
TEST: FUNCTION ONLY APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: FOLLOWS DOWN WHEN SAFETY IS PUSHED OFF.

INCIDENT: _____

COMMENTS: THE DIMENSION FROM THE TOP OF THE TRIGGER TO CENTER OF TRIGGER PIN HOLE BEING .011 OVERSIZE ELIMINATES MOST OF THE CLEARANCE NEEDED FOR THE TRIGGER-CONNECTOR TO RETRACT WITH THE SAFETY ON.

PLAINTIFF'S
EXHIBIT
3307

101

AL 0029842