

Dale Danner

From: Danner, Dale
Sent: 01/05/2001 08:41:52 AM
To: Snedeker, Jim; Reesor, Phillip K.; Golemboski, Matt R.
CC: Franz, Scott; Zajk, Joseph J
BCC:
Subject: RE: TLW0395

Need to repeat the adjustment test as well as the drop/jar/rotation work. . . . aka does the iron sight system have sufficient adjustment to cover manufacturing variance. Probably should do the assessment on all 10 pieces to prove that all 10 can be adjusted to bring POI to POA.

>-----

>From: Golemboski, Matt R.
>Sent: Friday, January 05, 2001 7:57 AM
>To: Snedeker, Jim; Reesor, Phillip K.; Danner, Dale
>Cc: Franz, Scott; Zajk, Joseph J
>Subject: RE: TLW0395
>

>The intent of this test is to approve the M710 .30-06 sighted gun for shipment. All other drop testing is done with six guns. I would adhere to standard testing procedures. If any other testing has to be done to clear the sighted version for shipment, include that in the testing. If 4 of the guns are not needed, ship them back.

>

>-----Original Message-----

>From: Snedeker, Jim
>Sent: Thursday, January 04, 2001 9:16 AM
>To: Reesor, Phillip K.
>Cc: Franz, Scott; Golemboski, Matt R.
>Subject: TLW0395
>
>
>
>

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.060004422

ETE00002210