Scott Franz

From: Franz, Scott

Sent: 11/22/2000 01:33:33 PM

To: Bristol, Il Ronald H.; Russo, Al; Trull, John C.; Golemboski, Matt R.; Zajk, Joseph

J; Diaz, Danny; Keeney, Mike; Danner, Dale; Snedeker, Jim; Reesor, Phillip K.; Franz, Scott

CC: BCC:

Subject: RE: M/710 T & P Issues

Just a reminder that we have a conference call today at 4:00 pm. Eastern time to review the latest test results. Topics for discussion will be:

- Schedule update
- * Part breakages:

Bolt stop - 1 failure Bolt handle - 3 failures

1 during normal shooting

2 during abusive slam test - test stopped

- Extractor sticking 1 gun
- * SAAMI drop test on hold, can't adjust triggers to process minimum

The "worst" case sample for trigger position, side to side, was sent to Matt's attention Tuesday. Scopes have not yet been sent to Al Russo. Will go out either today or Monday.

```
>From: Franz, Scott
>Sent: Monday, November 20, 2000 11:42 AM
>To: Bristol, II Ronald H.; Russo, Al. Trull, John C.; Gelemboski, Matt R.; Zajk, Joseph J; Diaz, Danny; Keeney, Mike; Danner, Dale; Snedeker, Jim, Reeser, Phillip K.; Franz, Scott
                 RE: M/710 T & P Issues
>Subject:
>Importance: High
>One more topic to add to the list
                          ISS System - could move ISS from "On" to "Off" with a screw driver (1 gun)
        From: Franz, Scott
                Monday, November 20, 2000 10:46 AM
        Sent:
                 Bristol II Ronald H., Russo; Al; Trull, John C.; Golemboski, Matt R.; Zajk, Joseph J;
Diaz, Danny; Keeney, Mike; Danner, Dale; Snedeker, Jim; Reesor, Phillip K.; Franz, Scott
                         M/710 T & P Issues
        Subject:
        Importance:
                          High
>
        The following topics will be discussed in detail during the 4:00 pm conference call today.
                          Trigger Pull - Toward high side of spec.
                          Engagement High - As measured by E-town, different methods
                          (need to understand further)
>
                          * Grip Caps - Falling out during shooting
                          Scope Issues -
```