As far as Sunday activity I would just continue with the preliminary measurements on puns A-1 to A-20. After this you could do the Bore Sight Test on guns A-21 - A-30 (minus A-26). Do not adjust scope at any time, just shoot one 5-shot group using the same POA and save targets for measurement later. After the bore sight test you could do Preliminary measurements on these 10 guns to catch them up with the other 20. Call if you have any questions.

Scott

