м101		OUT OF SPECS		ACCURACY
M101	,	OUT OF SPECS MISCELLANEOUS	,	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER
MITOS	,	MISCELLANEOUS	,	DALANCE OF FIREARM 13 MECDED TO PERFORM PROPER
KEPAIK		DROKEN DART		DUTT DIATE / DECOTI DAD WYOWDDOKEN
MT03	,	BROKEN PART	,	BUTT PLATE / RECOIL PAD IS BROKEN
M104	,	OUT OF SPECS	,	CHAMBER ROUGH / RINGS / TEARS / TIGHT
M105	,	MISCELLANEOUS	,	CONSIGNED GUN
M106	,	MISCELLANEOUS	,	COULD NOT DURLICATE CUSTOMERS COMPLAINT
M107	,	MISCELLANEOUS	,	CREDIT RETURN
м108		MISCELLANEOUS		DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT
м109		OUT OF SPECS		DAMAGES CASES. BULLETS. OR SHELLS
M110		FUNCTION		FATLS TO FERE
м111	,	FTNTSH	•	FINISH IS DAMAGED ON TRIGGER GUARD/PLATE
M112	,	OUT OF SPECS	,	HEADSPACE TS EXCESSIVE
M112	,	OUT OF SPECS	,	MUZZLE NAMACE
M111	,	MISCELLANEOUS	,	NO COMMERCIONDENCE
MTT4	,	MISCELLANEOUS	,	NO COMMESTORDENCE
MTT2	,	MISCELLANEOUS	,	NO FAMILY EQUIND AT BENCH
WTTP	,	MISCELLANEOUS	,	PACKING
MTT/	,	FINISH	,	POOR FINISH BARREL
M118	,	FINISH	,	POOR FINISH - FORE END
м119	,	FINISH	,	POOR FINISH RECEIVER (OR FRAME)
M120		FINISH		POOR FINISH - STOCK
M121		OUT OF SPECS		RECEIVER IS MISCUT
M122		FINISH		RUSTED COMPONENT
M123	,	MISCELLANEOUS	' (FORWARD TO PRODUCT SERVICE FOR INSPECTION
M124	,	OUT OF SPECS		STIGHTS OFF CENTER
M125	,	PROVEN DART	' .SS	STOCK FRACKED
M126	,	ETNICH	, 2000	CTOCK MARRED
MT72	,	FINTSH	- 30000	TRANSPORT OF STORY SPECS
MTZ/	,	OUT OF SPECS	######################################	TREGGER PURE IS OUT OF FACTORY SPECS
MTZ8	,	OUT OF SPECS	9	CHAMBER DIKTY / RUSTY
M129	,	FUNCTION	*	FAILS TO EXTRACT
M130	,	OUT OF SPECS	,	HEADSRACE: AT MINIMUM
M131	,	FUNCTION	salti i i i i i i i i i i i i i i i i i i	LIGHT OR NO INDENT FROM FIRING PIN
м132	,	OUT OF SPECS		BLUING SALTS BLEEDING FROM METAL
M133		OUT OF SPECS		EXTRACTOR MISSING
M134		FUNCTION		FABILTY MAGAZINE
M135	•	OUT OF SPECS	,	TRIGGER CONNECTOR BINDS
M136	,	BROKEN PART	,	EXTRACTOR IS BROKEN
M137	,	FUNCTION	y Mari	EATING TO FIECT
M132	,	FUNCTION		WITE TO EJECT
MT30	,	OUT OF SPECE		WELLE NOT FEED PROPERLY
MT39	,	OUT OF SEECS	1.000	WARETON IS DIEFISH T TO OPEN
M140	,	MISCELLANEOUS	,	ACTION IS DIFFICULT TO OPEN
M141	,	FUNCTION		EXTRACTOR IS CATCHING ON SHELL HEAD
M142	,	FUNCTION	•	MAGAZINE DIFFICULT TO LOAD
M143	,	FINISH		POOR RECOIL PAD TO STOCK FIT
M144	,	OUT OF SPECS	,	ROLL MARKING VISIBLE INSIDE BORE
M145		BROKEN PART		BOLT HANDLE FELL OFF, BOLT IS BROKEN
M146	-	BROKEN PART		FORE END CRACKED
м147		OUT OF SPECS		FORE END FIT IS TOO TIGHT
м148	,	OUT OF SPECS	,	FORE END ETT IS TOO LOOSE
M1/10	,	ETNICH	,	EODE END MADDED
M150	,	PROVEN DADE	<	COTO CAD TO DAMAGED
M150	,	OPOUREN PART	9	ACTION DAD TO DEOVEN
MTOT	,	BRUKEN FARI	٠,	ACTION BAR 15 BROKEN
MT25	,	BROKEN PAR	,	EJECTOR BROKEN
MT23	,	BROKEN PART	,	RECEIVER PLUG SCREWS BROKEN
M154	9 (2000)	OUT OF SPECS	,	RECEIVER SCOPE MOUNT HOLES OFF CENTER
M155	.	OUT OF SPECS	,	ACCURACY BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER BUTT PLATE / RECOIL PAD IS BROKEN CHAMBER ROUGH RINGS / TEARS / TIGHT CONSIGNED GUN COULD NOT DUPLICATE CUSTOMERS COMPLAINT CREDIT RETHERN DAMAGES ASSES, BULLETS, OR SHELLS FAILS TO FIRE FINISH IS DAMAGED ON TRIGGER GUARD/PLATE HEADSPACE IS EXCESSIVE MUZZLE DAMAGE NO CORRESPONDENCE NO FAULT FOUND AT BENCH PACKING ERROR POOR FINISH BARREL POOR FINISH RECEIVER (OR FRAME) POOR FINISH STOCK RECEIVER IS MISCUT RUSTED COMPONENT FORWARD TO PRODUCT SERVICE FOR INSPECTION SIGHTS OFF CENTER STOCK CRACKED STOCK MARRED TRIGGER PULL IS OUT OF FACTORY SPECS CHAMBER DIERTY / RUSTY FAILS TO EXTRACT HEADSPACE AT MINIMUM LIGHT OR NO INDENT FROM FIRING PIN BLUING SALTS BLEEDING FROM METAL EXTRACTOR MISSING FAULTY MAGAZINE TRIGGER CONNECTOR BINDS EXTRACTOR IS BROKEN FAILS TO EJECT WILL NOT FEED PROPERLY RIFTING ROUGH / MISCUT / DAMAGED ACTION IS DIFFICULT TO OPEN EXTRACTOR TO ROUGH / MISCUT / DAMAGED ACTION IS DIFFICULT TO LOAD POOR RECOIL PAD TO STOCK FIT ROLL MARKING VISIBLE INSIDE BORE BOLT HANDLE FELL OFF, BOLT IS BROKEN FORE END CRACKED GORD FOR END LIT IS TOO TIGHT FORE END FIT IS TOO LOOSE FORE END HIT IS TOO LOOSE FORE END FIT IS TOO LOOSE FORE END HARRED GRIP CAP IS DAMAGED ACTION BAR IS BROKEN RECEIVER SCOPE MOUNT HOLES OFF CENTER BOLT FACE / SHROUD DAMAGED BORE IS HEAT CHECKED CHOKE TUBE CONCENTRICITY
м156		OUT OF SPECS	,	BORE IS HEAT CHECKED
M157	- 1000g	OUT OF SPECS	,	CHOKE TUBE CONCENTRICITY
M158		BROKEN PART		CHOKE TUBE CRACKED
м159	. 2000000	OUT OF SPECS		CHOKE TUBE THREADS DAMAGED
M160		FUNCTION	_	EJECTOR DOES NOT HAVE ENOUGH TENSION
M161		OUT OF SPECS	,	EJECTOR STUCK IN BOLT
M162		OUT OF SPECS	,	FIRING PIN HITS PRIMER OFF CENTER
M162		OUT OF SPECS	,	FREEBORE MISCUT / MIN
M164	*	OUT OF SPECS	,	EJECTOR IS LOOSE
MITOH	1000000	OUT ME SPECS	,	FULCION TO FOODE
	Notice Control of the	2000000		

```
OUT OF SPECS
OUT OF SPECS
M165
                                                  RIB DOES NOT ALIGN WITH RECEIVER
                                                  RIB IS DAMAGED
RIB LANDS ARE LOOSE
M166
                     BROKEN PART
M167
                                                  RIB SWEEPS TO THE LEFT
RIB SWEEPS TO THE RIGHT
SCOPE MOUNT THREADS UPSET IN RECEIVER
CAMO FINISH WORN/DAMAGED
M168
                     OUT OF SPECS
                     OUT OF SPECS
M169
M170
M171
                     OUT OF SPECS
                     FINISH
                                                  CLOSES HARD OVER SHELL
M172
                     FUNCTION
                     OUT OF SPECS
OUT OF SPECS
                                                  BARREL BRACKET OUT OF POSITION
M173
                                                  BOLT STOP STICKS
ISS BOLT LOCKED IN THE OPEN POSITION
RETURNED FOR RECALL/UPDATE
M174
M175
                     MISCELLANEOUS
M176
                     OUT OF SPECS
M177
                     OUT OF SPECS
                                                  STOCK NOT BEDDED PROPERLY
M178
                     OUT OF SPECS
                                                  TRIG ADJ SCREWS RESET; CANNOT READJUST
                                                  BARREL TO RECEIVER MISALIGNMENT
EXTRACTOR HITS INSIDE CHAMBER
                     OUT OF SPECS
M180
                     OUT OF SPECS
M181
                     FUNCTION
                                                  BURR AT RIM AREA OF CHAMBER
M182
                                                  CARRIER OUT OF ADJUSTMENT
                     FUNCTION
                                                  GAS ORIFICE HOLE IS OVERSIZE
MAGAZINE TUBE SEPARATED FROM RECEIVER
                     OUT OF SPECS
M183
M184
                     BROKEN PART
                                                  THREE SHOT PLUG AT WRONG END OF MAG TUBE ACTION SPRING TUBE FELL OFF
M185
                     MISCELLANEOUS
                     BROKEN PART
M186
                                                 ACTION SPRING TUBE FELL OFF
BARREL GUIDE STUD MISSING
BARREL SUPPORT SEPERATED FROM MAG TUBE
CARRIER LATCH IS BROKEN
GAS CYLINDER SEPERATED FROM BARREL
GAS HOLES OUT OF POSITION
MAG LATCH BROKEN / SEPARATED FROM HOUSING
CARRIER LATCH TAB OUT OF ADJUSTMENT
ACTION RAP OCK CATCHES RETWEEN ACTION RAP
                     BROKEN PART
M187
м188
                     BROKEN PART
м189
                     BROKEN PART
M190
                     BROKEN PART
M191
                     OUT OF SPECS
                     BROKEN PART
м192
M193
                     OUT OF SPECS
M194
                     FUNCTION
                                                  ACTION BAR LOCK CATCHES BETWEEN ACTION BAR AND
RECEIVER
                                                  ACTION CLOSES TOO EASILY ACTUATING ROD BENT/LOOSE
M195
                     MISCELLANEOUS
м196
                     FUNCTION
                                                  CHOKE TUBE CONCENTRICITY - BOTTOM BARREL CHOKE TUBE CONCENTRICITY - TOP BARREL
M197
                     OUT OF SPECS
M198
                     OUT OF SPECS
м199
                     FUNCTION
                                                  COCKING RODS BIND
M200
                     MISCELLANEQU'S
                                                  DEBRIS UNDER REAR CONNECTOR
M201
                     FUNCTION
                                                  DOUBLES
M202
                     FUNCTION
                                                  EJECTOR - BOTTOM BARREL EJECTS TOO SOON
                                                  EJECTOR SEAR OUT OF ADJUSTMENT
EJECTOR SEAR TOO LONG
                     OUT OF SPECS
M203
M204
M205
                                                  EJECTOR SYSTEM HAS INCORRECT TIMING
                     FUNCTION
                                                  EJECTORS BIND
M206
                     FUNCTION
M207
                                                  FAILS TO COCK
                     FUNCTION
                     FUNCTION
OUT OF SPECS
BROKEN PART
                                                  FIRING PINS BIND IN FRAME
M208
                                                  FRAME FACE IS ROUGH/FIRING PIN HOLES RECESSED
M209
                                                  GAS CYL CRACKED
M210
                                                  GUN RECEIVED IN MANUAL SAFETY MODE
GUN RECEIVED WITH SAFETY LOCKED OFF
M211
                     MISCELLANEOUS
                     MISCELLANEOUS
M212
                                                  HAMMERS DO NOT COCK - NO OVERCOCK
INTERCEPTOR LATCH STUD MISSING
                     FUNCTION
BROKEN PART
M213
M214
                                                  LOCKING BOLT OVERLOCK
M215
                     FUNCTION
M216
                     FUNCTION
                                                  OPENS WHEN FIRED
                     OUT OF SPECS
M217
                                                  OVER LOCKED
M218
                                                  PREPLAY ON SEAR NOT TO FACTORY SPECIFICATIONS
M219
                     MISCELLANEOUS
                                                  CARDBOARD PACKING RING WAS NOT REMOVED
M220
                     MISCELLANEOUS
                                                  PISTON/PISTON SEAL INCORRECTLY INSTALLED
M221
                     OUT OF SPECS
                                                  RECEIVER FEED CUTS ARE ROUGH
M222
                     MISCELLANEOUS
                                                  MODIFY TUBE CAPACITY TO ACCEPT TEN ROUNDS
M223
                     BROKEN PART
                                                  ACTION TUBE RING BROKEN
M224
                     OUT OF SPECS
                                                  BREECH PLUG FROZEN IN BREECH
                      BROKEN PART
                                                  EJECTOR SPRING IS BROKEN
M226
                     OUT OF SPECS
                                                  FORE END TUBE NUT IS LOOSE - FORE END RUBS
BARREL
M227
                     BROKEN PART
                                                  GAS BLOCK SEPERATED FROM BARREL
```

				Medicinitists, Committee and C
M228		BROKEN PART		GUIDE RING SEPERATED FROM BARREL
M229	,	OUT OF SPECS	,	MAGAZINE GUIDE IS OUT OF POSITION
M230		BROKEN PART		LOCKING BAR ASSEMBLY BROKEN
M231		OUT OF SPECS		NIPPLE NOT TO FACTORY SPECIFICATIONS
M232		OUT OF SPECS		RECEIVER INSERT IS MISSING
м233	,	OUT OF SPECS	,	RESIZE BORE
M234		BROKEN PART		RECEIVER BROKEN AT BARREL CLAMP
M235	,	OUT OF SPECS	•	RESIZE BORE
M236	,	BROKEN PART	,	RECEIVER BROKEN AT BARREL CLAMP
M237		BROKEN PART		INSTALL NEW BOLT ASSM
M238	,	UPDATE PROG	,	CLEAN & INSPECT
M239		UPDATE PROG		REPLACE TRIGGER ASSEMBLY
M240	,	UPDATE PROG	,	BOLT LOCK SAFETY MODIFICATION
M241		MISCELLANEOUS		RETURNING GUN TO FACTORY
м990	,	BROKEN PART	,	USER DEFINED
м991	,	FINISH	,	USER DEFINED
м992	,	FUNCTION	,	USER DEFINED
м993	,	MISCELLANEOUS	,	USER DEFINED
м994	,	OUT OF SPECS	,	USER DEFINED
м995	,	UPDATE PROG	,	USER DEFINED