

Trigger-connector failure on Remington Mod 700.

Discussion Thread

Response (Laura) 6/14/2000 7:06:10 PM
At 06/14/2000 04:04 PM we wrote -
Dear Sir,
According to our International Parts Representatives, Khalahari Arms can
obtain this part for you.

Customer 6/13/2000 9:53:06 AM

===== application File Attachment =====
RemingtonArms.doc, 25600 bytes, added to incident