Hi A couple of years ago I purcased a new remington 700 in the 270 caliber. M...

Discussion Thread

Response (Inez) 10/9/2002 3:46:56 PM. There are currently no recalls on the Model 700 center fire rifles. We do have a bolt lock modification program for the Model 700 series rifles that were manufactured prior to 1982, which had the bolt lock safety. This means on the guns manufactured prior to 1982 they have an old style safety that must be placed in the F or Fire position in order to load and unload the firearm.

we apologize for any inconvenience you may be experiencing. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

http://www.remington.com/Support/repairsvc/ModelSelection.asp

Thanks-Melissa

Customer (David Rhoton)

10/5/2002 11:31:40 AM

A couple of years ago I purcased a new remington 700 in the 270 caliber. My question is that the safety is almost impossible to operate and was wondering if a recall was every out and how do I go about about getting this fixed?

Could you e-mail me and let me know about this problem? Thanks

David Rhoton anzil@chartertn.net