Can you tell me exactly when my model 700 was manufactured? Here are some fea...

Discussion Thread Response (Laura)

10/16/2002 3:15:19 PM

Dear Brian, Thank you for your inquiry. According to the information provided, this firearm was manufactured in or around 1962. These firearms do not accept stripper clips. You can send the stock to our factory for refinishing. We also want to make you aware of a safety modification program that we are offering on these and other Model 700 rifles. You can view this information regarding this through the front page of our website or through the link

below: http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (Brian Calvert) 10/13/2002 11:54:06 AM Can you tell me exactly when my model 700 was manufactured? Here are some features: the receiver is drilled and tapped on the left and at the rear for receiver sights, the receiver is also notched in front of the rear scope mount holes for what I assume is stripper clip loading, the barrel is 20 inches long, the barrel is marked "Remington Arms Co.Inc., Ilion, N.Y. Made in U.S.A. Pat. No. 2,473,373 2,514,981 30-06 SPRG, at the rear of the barrel on the left side just in front of the recoil lug it is marked P J 46. I need to know: 1) when exactly was this rifle manufactured? e.g. March 1973 2) Is the notch/slot on the receiver for stripper clip loading? 3) Can Remington refinish this stock? Thank you so much for you time in helping me solve these mysteries!

