i have a modle 600 mohawk 243 and it has recently started fireing when i clos...

**Discussion Thread** 

Response (Chris) 1/29/2003 2:08:25 PM Dear Mr. Chase, In 1979, Remington instituted a recall for Model 600 and 660 rifles made before February, 1975, because, under certain chroumstances, the safety and trigger could be manipulated in a way that could result in an accidental discharge. Under the 1979 recall program, owners of the affected rifles could return their guns for installation of a new trigger assembly at no charge. Since 1979, thousands of the affected firearms have been serviced under the 1979 recall and received new trigger assemblies.

To view more information on this issue and instructions for sending the firearm to our factory, go to: http://www.remington.com/Safety\_Modification\_Program/600\_660.htm

Customer (Byron Chase) 1/19/2003 11:17:15 PM i have a modle 600 mohawk 243 and it has recently started fireing when i close the bolt. i was told that there was a recall on them and was wundering if this was what the recall was about and what might be the problem with my rirle?

Subject to Protective Order - Williams v. Remington