Recall? I was just informed that maybe the trigger assembly on $m_{\rm X}$ mohawk $600\,\dots$

Discussion Thread

Response (Chris) Dear Troy, 3/28/2003 10:42:51 AM

Thank you for contacting Remington Country. Your Model 600 was produced in 1976 and is not included in the recall.

If you have not had the firearm cleaned or inspected recently, we recommend taking it to on of our Remington Authorized Repair Centers for a thorough cleaning and safety inspection.

You can locate your nearest repair center by wisiting the Repair Information Center in our Support Section and selecting your model and state:

http://www.remington.com/repairsvc/ModelSelection.asp

Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety_McdlFication_Program/remington_safety.htm

Customer (Troy Kanderka) 3/27/2003 8:06:15 PM
Recall? I was just informed that maybe the trigger assembly on my mohawk
600 308 win
is recalled? What do I do?
Thuks
Troy (Canada)

