

Discussion Thread

Response (Jessica) Dear Sean, 7/7/2004 9:02:14 AM

We regret that you are experiencing problems with your trigger, however, these parts are not sold seperate. Based on the information you have provided, we suggest that you send your firears to our Ilion, NY facility.

For U.S. repairs, please follow these guidelines:

- 1. Record the serial number of your firearm before sending it to us.
- 2. Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box, not a hardcase.
- 3. Remove all accessories from your firearm to prevent loss or damage. This would include scope, slings, or extra choke tubes.
- 4. Enclose a letter with the firearm detailing the model name or number of your firearm and serial number along with a full description of the problem. Be sure to include your full name and address (P.O. Box and Street Address), including zip code, daytime telephone number, and e-mail address.
- 5. Ship your firearm by either United Parcel Service (UPS) or Parcel Post (US Post Office). Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. Customer is responsible for shipping charges to the factory.

For U.S. repairs only, ship to:

Remington Arms Company, Inc. Attn: Arms Services Division/Repairs 14 Hoefler Avenue Ilion, NY 13357

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TEEEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

If you have any questions as to the warranty on Remington firearms, please refer to our Firearms Warranty .

Customer (seabn muratugh)
Hello,

7/5/2004 1:14:11 PM

I need a replacement trigger overtravel screw for my Model 700 rifle. The head snapped in two. Please let me know how I would obtain one.

Thanks,

Sean