

Triggers on Sportsman 78 rifles

Discussion Thread

Response (Chris)
Dear Mr. Goltra,

10/7/2004 4:27:44 PM

Thank you for contacting Remington Country. Your Model 700 was produced in 1984. Your firearm has not been involved in a recall. Your rifle may have been originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (John Goltra)

10/2/2004 11:33:48 PM

I have just purchased a used Sportsman 78 rifle in 30-06 calibre and read that a few of the production run in 1987 were recalled due to a defective part in the trigger mechanism. Does my rifle fall into this group? the serial number is 86641874. Thanks. John Goltra