Model 600

Discussion Thread

Response (Chris) 2/7/2005 3:46:03 PM

Dear Mr. Holmes,

Thank you for your inquiry. By the serial number, your XP100 was produced around 1982. It has not been involved in a recall and does not have the bolt lock.

Customer (Jim Holmes) 2/2/2005 3:37:56 PM

> Thank you for the response. As this rifle is in another state with my yearndson right now, I will not be able to followup on serial number at this time. We will find an authorized Remington repair site as instructed

> and go further. Thank you again. Incidentally, I still need to know if the XP100 is subject to this problem. My XP is the 7MM BR version, serial number B7517725. Thanks for any help you can offer.

Jim Holmes