

From: O'Steen, Norma Sent: 08/31/2005 02:33:19 PM

To: Mitchell, Christy

CC:

BCC:

Subject: RE: Emailing: 710.htm

The website does not say ANY Remington Authorized Repair Center and it goes on to say call us first.

From: Mitchell, Christy

Sent: Wednesday, August 31, 2005 2:21 PM

To: O'Steen, Norma; Chilton, Inez Subject: Emailing: 710.htm

The internet tells them that it should be inspected at a Rennington Authorized Repair Center.

This is Remington Country... <a href="http://www.remington.com/">http://www.remington.com/</a>

HOME <a href="http://www.remington.com/">http://www.remington.com/safety/safety.htm> MAGAZINE <a href="http://www.remington.com/safety/safety.htm">http://www.remington.com/safety/safety.htm> MAGAZINE <a href="http://www.remington.com/safety/safety.htm">http://www.remington.com/safety/safety.htm> AMMUNITION <a href="http://www.remington.com/ammo/ammofr.htm">http://www.remington.com/safety/safety.htm> AMMUNITION <a href="http://www.remington.com/ammofr.htm">http://www.remington.com/safety/safety.htm> AMMUNITION <a href="http://www.remington.com/accessories/accessories/r.htm">http://www.remington.com/accessories/r.htm> OTHER PRODUCTS <a href="http://www.remington.com/other/products.htm">http://www.remington.com/safety/safety.htm> SUPPORT <a href="http://www.remington.com/support/support.htm">http://www.remington.com/support/support.htm></a> <a href="http://www.remington.com/support/support.htm">http://www.remington.com/support/support.htm</a> <a href="http://www.remington.com/support.htm">http://www.remington.com/support.htm</a> <a href="http://www.remington.com/support.htm">http://www.remington.

Safety <a href="http://www.remington.com/safety/">http://www.remington.com/safety/</a>

10 Commandments <a href="http://www.remington.com/safety/10+Commandments/">http://www.remington.com/safety/10+Commandments/</a>

Online Courses <a href="http://www.ternington.com/safety/Courses/">http://www.ternington.com/safety/Courses/</a>

Firearm Care <a href="http://www.remington.com/safety/FirearmCare/">http://www.remington.com/safety/FirearmCare/</a>

Repairs <a href="http://www.remington.com/safety/Repairs/">http://www.remington.com/safety/Repairs/>

MSDS <a href="http://www.remington.com/safety/MSDS/">http://www.remington.com/safety/MSDS/>

Education <a href="http://www.remington.com/safety/Education/">http://www.remington.com/safety/Education/</a>

Partners B2B <a href="http://www.remington.com/partner/">http://www.remington.com/partner/</a>

Retail Locator <a href="http://remington-locator.custhelp.com">http://remington-locator.custhelp.com</a>

About Us <a href="http://www.remington.com/aboutus/">http://www.remington.com/aboutus/</a>

Site Map <a href="http://www.remington.com/sitemap">http://www.remington.com/sitemap</a>

Win this Gun!

<a href="http://www.remington.com/sweepstakes/magazine\_contest.htm">http://www.remington.com/sweepstakes/magazine\_contest.htm</a> Custom Maps <a href="http://www.mytopo.com/index.cfm?pid=remington">http://www.mytopo.com/index.cfm?pid=remington</a>

Home <a href="http://www.remington.com/">Home <a href="http://www.remington.com/safety/">Home <a href="http://www.remington.com/safety/710/">Hottp://www.remington.com/safety/710/</a> : Safety Notice

Remington Safety

MODEL 710(r) PRODUCT SAFETY WARNING AND RECALL NOTICE

Remington Arms Company, Inc is voluntarily recalling a limited number of Model 710 bolt-action rifles as a result of its discovery, during routine test firing, that some Model 710 rifles manufactured between July and October 2002 may have been assembled with an improperly made "Safety Detent Spring." Although unlikely, there is a possibility that the manual safety arm mechanism in such a rifle could fail to fully return to the "safe" or "on" position.

If you own a Model 710 rifle please enter your serial number below to determine if your firearm needs to be inspected or repaired as part of the recall.

Enter your Model 710 serial number

Bottom of Form

WARNING: Use of a rifle with an improperly functioning safety could lead to an accidental discharge, resulting in personal injury, death or properly damage. Owners of Model 710 rifles subject to this recall should not attempt to diagnose or repair their rifles themselves.

No other Model 710 rifles, or other models of Remington firearms, are subject to this recall.

Anyone who currently owns or possesses a Model 710 Rifle subject to this recall, or who purchased one and gave it or sold it to another party, should contact Remington immediately by calling 1-800-243-9700, or 1-336-548-8700, Monday through Friday 9 AM - 5PM EST. Remington will assist you in making arrangement to have your rifle inspected and/or repaired by a Remington Authorized Repair Center at no charge to you. To expedite repair program, Remington will send shipping tags to each customer and will cover all related shipping and repair charges. Please do not return your rifle to a Remington Authorized Repair Facility before contacting Remington on the toll-free hotline.

Remington apologizes for this inconvenience, but wants its customers to enjoy the shooting sports safely. It is important, therefore, that owners of Model 710 rifles subject to this recall participate in this program and do not use their rifles before they have been inspected and or repaired.

Safety and safe firearms handling is everyone's responsibility

Privacy Policy <a href="http://www.remington.com/aboutus/privacy.fitm">http://www.remington.com/aboutus/privacy.fitm</a> [Terms of Use <a href="http://www.remington.com">http://www.remington.com</a> (c)2005 Remington Arms Company fitm: All Rights Reserved. www.remington.com

www.remington.com <a href="http://www.remington.com">www.remington.com</a> www.remingtonmilitary.com <a href="http://www.remingtonmilitary.com">http://www.remingtonmilitary.com</a> www.remingtontd.com <a href="http://www.remingtonpmpd.com">http://www.remingtonpmpd.com</a> <a href="http://www.remingtonpmpd.com">h

