

Home

Home: Safety: Model 710: Safety Notice

Model 710

Model 710

Model 710

Model 710

Model 710

Model 710

Model 710


Model 710

Model 710

Model 710

Model 710

Model 710



## MODEL 710® PRODUCT SAFETY WARNING AND RECALL NOTICE

Remington Arms Company, Inc. is voluntarily recalling a limited number of **Model 710 bolt-action rifles** as a result of its discovery, during routine test firing, that some Model 710 rifles **manufactured between July and October 2002** may have been assembled with an improperly made "Safety Detent Spring." Although unlikely, there is a possibility that the manual safety arm mechanism in such a rifle could fail to fully return to the "safe" or "on" position.

If you own a Model 710 rifle please enter your serial number below to determine if your firearm needs to be inspected or repaired as part of the recall.

**Enter your Model 710 serial number:**

**WARNING:** Use of a rifle with an improperly functioning safety could lead to an accidental discharge, resulting in personal injury, death or property damage. Owners of Model 710 rifles subject to this recall should **not** attempt to diagnose or repair their rifles themselves.

No other Model 710 rifles, or other models of Remington firearms, are subject to this recall.

Anyone who currently owns or possesses a Model 710 Rifle subject to this recall, or who purchased one and gave it or sold it to another party, should contact Remington immediately by calling **1-800-243-9700, or 1-336-548-8700, Monday through Friday 9 AM – 5PM EST.** Remington will assist you in making arrangement to have your rifle inspected and/or repaired by a Remington Authorized Repair Center at no charge to you. To expedite repair program, Remington will send shipping tags to each customer and will cover all related shipping and repair charges. **Please do not** return your rifle to a Remington Authorized Repair Facility before contacting Remington on the toll-free hotline.

Remington apologizes for this inconvenience, but wants its customers to enjoy the shooting sports **safely**. It is important, therefore, that owners of Model 710 rifles subject to this recall participate in this program and do not use their rifles before they have been inspected and or repaired.

**Safety and safe firearms handling is everyone's responsibility.**

