

Bolt Action Centerfire – Bolt Lock Update Modification Program

Website text

Remington is offering a **safety modification program** to remove the bolt lock mechanism for certain Remington bolt-action centerfire firearms made prior to 1982. (Post 1982 bolt-action firearms were not manufactured bolt-lock mechanisms). To determine whether your firearm has a bolt-lock mechanism and is subject to the **safety modification program**, "click" on the model listed below and follow the directions. Most bolt-action firearms with a bolt lock mechanism cannot be unloaded unless the manual safety switch is in the "F" or "fire" position. If you participate in the program your firearm will be modified to eliminate the bolt-lock feature. The operation of your firearm will not otherwise be affected. [insert link to announcement]

Here are the basic program elements:

- The firearms will be cleaned and inspected and the bolt lock mechanism will be removed for \$20.00 plus shipping and handling.
- We will return the gun to you with a \$20.00 rebate coupon good towards the purchase of any Remington brand safety product (eye protection, hearing protection, cable and trigger locks, gun cabinets and gun safes.)

Please click on the centerfire model listed to obtain more information on the program for the specific model, as there are some differences in the program based on the model type

- Insert picture of model 700
- Insert picture of model 600
- Insert picture of model 660
- Insert picture of model 721
- Insert picture of model 722
- Insert picture of model 725
- Insert picture of model 788
- Insert picture of model XP-100
- Insert picture of model 40-X
- Insert picture of model Seven
- Insert picture of model 710
- Insert picture of model 30, 30 Express

6/12/2006

1